



RAM Aircraft, L.P.
Service Letter **SL2020-01**

June 1, 2020

To whom it may concern,

RAM Aircraft STC SA2375SW has been amended to include the new Airplane Flight Manual Supplement 1177. Airplane Flight Manual Supplement 1177 was created to specify the oil capacity marking on the engine oil filler cap.

Airplane Flight Manual Supplement 1177 is specifically applicable to Cessna model 172N airplanes equipped with the Textron (Lycoming) O-320-D2G engine, O-320-D2J engine or O-320-E2D engine (as modified by RAM Aircraft STC SE3692SW) in accordance with RAM Aircraft STC SA2375SW.

Airplane Flight Manual Supplement 1177 is FAA approved and must be attached to the FAA-approved Airplane Flight Manual when the aircraft has been modified in accordance with RAM Aircraft STC SA2375SW. The information contained in Airplane Flight Manual Supplement 1177 supplements or supersedes the Airplane Flight Manual only in those areas listed therein. For limitations, procedures, and performance not contained in Airplane Flight Manual Supplement 1177, consult the Airplane Flight Manual.

For further information, contact RAM Aircraft Customer Service at (254) 752-8381.

Best regards,

A handwritten signature in blue ink that reads "Rick Roper".

Rick Roper
Director of Operations
RAM Aircraft Limited Partnership
P.O. Box 5219 / 7505 Karl May Road
Waco Regional Airport
Waco, TX 76708
www.ramaircraft.com