

Exchange Core Policy: Engine, crankcase, crankshaft, internal gears, exhaust, accessories, propeller, governor, and hardware items are only sold on an exchange basis, based upon the customer's exchange of like type and normal runout cores as removed from subject aircraft, and serviceable to RAM's overhaul specifications. Cores should be returned within 30 days of RAM OHE engine shipment, or immediately with a RAM installation. Non-serviceable core fees will be due and payable to RAM.

Installation and Set-up

- Each aircraft receives a detailed preflight and high altitude flight inspection to ensure airworthiness and to document performance of instruments, flight controls, landing gear, accessories, lights, and avionics.
- Discrepancies are brought to customer's attention. Unairworthy items must be repaired at customer's expense during RAM proceedings in order for RAM to set up, fly, and deliver the finished product.
- Old engine is removed. Engine bed is cleaned. Mount structure is inspected and corrosion treated. Four hours labor is standard.
- Due to its tendency to contaminate the engine oil supply, if installed, the propeller unfeathering accumulator will be disabled unless optionally replaced with a newer unit. OHE: \$875
- Applicable one engine installation parts are installed.
- Engine is installed and set up, which includes multiple high altitude test flights. Fuel for flying both engines is included; however, adjustments or maintenance to the remaining engine, or to the aircraft, are not included in this package price.
- Aircraft washed. Interior cleaned prior to delivery and customer acceptance.
- Remove, clean, and reinstall the air/oil separators on all 421C and late model 421B (after serial number 500).

Optional Parts and Engine Installation Items

- **New 100 amp Alternator Package:**
Hartzell Engine Technologies ALV9610 with nut, thrust washer, cotter key, and New PMA Alternator clutch. When purchased with an engine RAM will install for no additional cost. (Retail \$2,444) Only when purchased with a RAM engine: **\$1,62** each - Exchange
- **Cooling Shroud Kit** for dry vacuum pump - New: \$55 each

One Engine

Installation at RAM: \$72,097 exchange

- **RAM OHE CMI GTSIO-520-L engine**
- **Installation Parts - Included**
- **Installation and Set-up**
- **Reuse Customer's propeller and governor**
[Propeller and governor must be airworthy.]

RAM Aircraft, LP • 7505 Karl May Drive • P.O. Box 5219 • Waco, TX 76708
Phone: (254) 752-8381 • Fax: (254) 752-3307 • www.ramaircraft.com

